

## **No Start After Replacing Ford PCM**

**Application:** 

1996 and later Ford vehicles with Passive Anti-Thief System (PATS).

**Problem:** 

After replacing the PCM, the engine may crank and even fire initially, but die almost immediately.

Cause:

Certain Ford vehicles incorporate the Passive Anti-Thief System (PATS). This security feature immobilizes the vehicle by disabling the fuel pump, injectors and possibly the starter, until the ignition key relearn is performed on the car.

Solution:

Motorcraft Service provides a reference chart that identifies all Ford PATS vehicles. It also provides a Flash User Manual that describes the requirements and procedures needed to Flash and reset PATS after the ECM has been replaced. To access this information online, please follow these steps:

- 1. Go to www.motorcraftservice.com
- 2. Access your subscriptions
- 3. Select "Reprogramming and Initialization"
- 4. Select the "Initialization (PATS) Information" section
- 5. Then select and download the Passive Anti-Theft System Chart
- 6. Locate and download the user manual in the "Ford Module Programming Application" section.

The chart identifies PATS vehicles and outlines the procedures and requirements needed to do PATS. A thumbnail of the PATS chart is below. This information, along with a valid Ford Module Program subscription and an All-Makes Flash Reprogrammer will enable you to conduct the PATS relearn.

Fird Passive Anti-Theft								
	Vehicle	Model Year (1996-2007)	PATS Control Function Type	Max Keys	Minimum Keys Required	Starter Interrupt Present	Theft Indicator Flashes at Ignition OFF	Parar Re:
	Contour (V6 Only)	98 (before 2/2/98)	А	16	1	Yes	Yes	N/
П	, , , , ,	98 (2/2/98 build or later)-00	Е	8	2	Yes	Yes	N/
П	Crown Victoria	98-02	В	8	2	No	Yes	#
Ш		03-07	Е	8	2 or 3	Yes	Yes	N/
	Edge	07	С	8	2	Yes	Yes	#
	Escape	01-04	Е	8	2	Yes	Yes	N/
		05-07	Е	8	2	Yes	Yes	N/
	Escape HEV	06-07	F	8	2	No	Yes	#1
	Excursion	00-05	В	8	2	No	Yes	#

Note:

This Tech Tip bulletin is supplied as technical information only and is not an authorization for repair.

JDB1007 TT 70-78-0001N