-FLA-H- REPROGRAMMING	NAPA SUPPORTIN	IG TODAY'S PROFESSION	TAL TECHNICIAN
	Chrysler VIN Prog	gramming - Cas	e Matters
Application:	All Chrysler Flash ECM's requ	uiring VIN programming.	
Problem:	After replacing the ECM, the or bad VIN (84) get set.	ABS light stays on, or coo	des for ABS, Air Bag,
Cause:	Incorrect VIN is stored in ECM programmed into the replace entered in with UPPER CASE	ment ECM. Additionally, t	he VIN must be
	Incorrect: 1b7kf23z0wj24351	7 Correct: 1B7K	F23Z0WJ243517
Solution:	Use the Flash2 All-Makes F programmed VIN as follow		nd verify the
select Reprogram I	Res Reprogrammer, select Chrysler, ECM, and then select Modify VIN.		eld. BE SURE TO CASE. Select SET VIN.
3. The message "Set received. Select O		match number enter are returned, check and correct VIN. If repeat steps 2,3 ar	