



## SERVICE AND APPLICATION NOTES

IAQ-16-01  
April 18, 2016

### GDX-01 (Y2171) Controller Software Issue

#### AFFECTED PRODUCTS

The HRV/ERV units sold with the Y2171 Controller that are listed in tables 1 and 2 are affected.

#### ISSUE AND SOLUTION

#### CANADA

We have been informed that 42 HRV/ERV units shipped in Canada from August 2015 to October 2015 will have a Y2171 Digital controller that has software issue. After four months of operation a "Service" text will appear on the display. There is no method to clear the text from the screen so the control must be replaced. **The operation of the system is not affected by this software issue.**

TABLE 1. CANADA SHIPMENT LOCATIONS

Date	Location	Quantity	Model	Serial Numbers
Sept 8	Brampton	10	HRV5-150-GDX (Y6420)	2315J33438 through 2315J33447
Sept 21	Brampton	2	HRV3-150-TPD-GDX (Y6423)	2315J35603 and 2315J35606
Oct 19	Brampton	10	HRV5-150-GDX (Y6420)	2315K39475 through 2315K39484
Oct 27	Brampton	10	HRV5-150-GDX (Y6420)	2315K41598 through 2315K41607
Oct 27	Calgary	10	HRV5-150-GDX (Y6420)	2315K41608 through 2315K41617




Figure 1. Service Indicator

## UNITED STATES:

Units shipped to United States destinations do not include the GDX-01 (Y2171). However a total of 73 GDX-01 controls have shipped to the following locations:

TABLE 2. UNITED STATES SHIPMENT LOCATIONS

Date	Location	Quantity
Aug 12	Grow City, OH	1
Aug 26	Grow City, OH	2
Aug 26	Grow City, OH	1
Sep 10	Grow City, OH	1
Aug 13	Marshalltown, IA	2
Aug 19	Marshalltown, IA	9
Aug 25	Marshalltown, IA	2
Aug 26	Marshalltown, IA	3
Sep 4	Marshalltown, IA	3
Sep 15	Marshalltown, IA	3
Sep 29	Marshalltown, IA	3
Oct 7	Marshalltown, IA	3
Oct 30	Marshalltown, IA	2
Aug 14	Eastvale, CA	9
Aug 31	Eastvale, CA	2
Sep 4	Eastvale, CA	1
Sep 16	Eastvale, CA	2
Sep 25	Eastvale, CA	5
Sep 30	Eastvale, CA	2
Sep 30	Eastvale, CA	6
Oct 15	Eastvale, CA	3
Aug 24	Middleton, PA	2
Sept 4	Middleton, PA	1
Oct 8	Middleton, PA	1
Oct 19	Madonna, GA	1
Oct 28	Middleton, PA	1
Oct 20	McDonough, GA	2
TOTAL		73

**NOTE:** At this time we believe due to volume and replacement orders that the Lennox GDX-01 control inventory is no longer available.

### RECOMMENDED FIELD ACTION

In all cases the replacement of the control will be required. Please return the control for warranty replacement.

### LONG TERM CORRECTION

Software corrections have already been made. Please note the "Service" text does not in any way affect system operations.