

## **Honda Civic 1.8L 4-Cyl., 2006** Part Number 39054K

- Accessory drive belt routing produces excessive force on tensioner causing tensioner misalignment, belt noise and possible tensioner bolt failure.
- Kit includes specially-constructed new length belt, upgraded tensioner, upgraded tensioner bolt and new belt routing under hood sticker.
- New belt length and construction allow for new belt routing reducing force on tensioner and tensioner bolt.

*Reference Technical Service Bulletin: 09-007*

