

**Application:** All power steering equipped vehicles.

**Problem:** Premature failure of power steering components.

Cause:

Particles not removed during the flushing process or particles fromeveryday wear of components and hoses cause valves to stick and

block fluid flow.

When replacing any power steering component, always flush the entire system and then install an in-line filter such shown below (part 81-0589F).

Be sure to use OE recommended or equivalent fluid.



In-Line Filter 81-0589F

**Note:** This Tech Tip bulletin is supplied as technical information only and is not an authorization for repair.

JDB0354 TT 20-0003AN