Chrysler, Dodge & Plymouth Mini-Van 3.0L-3.8L V6, 1993-2000 **Part numbers 38342K, 38379K & 38398K**

- Under rain or snow conditions the serpentine belt could come off leaving your customer stranded.
- Kit includes double-sided Micro-V® Belt, grooved idler pulley and tensioner with a grooved pulley.
- Delivers the proper tension and performance to the belt drive system making it virtually impossible for the belt to jump off.

Reference Technical Service Bulletin: TSB 07-01-99 & 07-02-94