

NBF

Standing Height Desk
Assembly Instructions




O-EHD1260D


PART LIST



Frame(1x)




Side Leg (2x)




Desk top with 2 grommet(1x)

NBF				
Assembly HARDWARE				
S/N	PICTURE	NAME	TOTAL QTY	REMARK
A		M8*35 Leg screw	4PCS	
B		6M Wrench	1PCS	
C		M6*19 Top screw	8PCS	

1. INSTALL SIDE FRAME & LEGS USING "A" LEG SCREWS, THEN TIGHTEN WITH "B" WRENCH.
   A(4x)
   B(1X)



2. CONNECT DESK TOP TO FRAME USING "C" TOP SCREWS, USE POWER DRILL FOR CONNECTION.
C (8X)



3. COMPLETE.

