INTEGRATED TIC **QUICK START GUIDE**

MSA — The Safety Company

Power on the G1 SCBA

TO BEGIN:
Insert the G1 battery into the Backplate & Power Module Assembly

OPTION 1:
Pressurize the SCBA

OPTION 2:
Press & hold the red manual alarm button

Green buttons located on sides

Red button located on front

Note: For options 1 and 2, the G1 battery must be installed

Note: To clear the alarm double press the green buttons

Enter / Exit TIC Mode

Enter or Exit TIC mode by pressing & holding either of the 2 green buttons (long press for approximately 2 seconds)

Press green button located on either side for 2 seconds

LEFT SIDE

Press green button located on either side for 2 seconds

RIGHT SIDE

Note: G1 can be configured to enter TIC Mode automatically when the SCBA is powered on via the A2 Software. Powering off the G1 SCBA will also exit TIC Mode

Changing TIC Palettes

When in TIC mode, change palettes by pressing either of the 2 green buttons (short presses)

Press green button located on either side (short presses)

LEFT SIDE

Press green button located on either side (short presses)

RIGHT SIDE

Note: Integrated TICs are preconfigured with 5 default palettes; alternative palettes and palette order can be configured via the A2 Software