

Toyota Camry, Solara & Highlander, RAV4 2.4L 4-cyl., 2001-2004 Part number 38216K

- Noise from engine compartment during vehicle operation, especially after cold soak.
- Kit includes specially-constructed belt and upgraded tensioner.
- Provides proper tension and belt surface to correct problem.

Reference Technical Service Bulletin: TSB EG040-04

