




Tru-Flow™ Water Pumps

Water Pump Spanner Wrench



Get a Grip on Water Pump Replacement

The NAPA Tru-Flow™ Water Pump 2 1/2" Spanner Wrench (Part No. 91060) adapts to a 3/8" drive ratchet or breaker bar to help you do your job faster and easier. The spanner lets you get a firm grip on the water pump pulley so that you can move the fan clutch without scratching or galling the pulley or damaging the mating components.

The Spanner Wrench fits several NAPA Tru-Flow™ Water Pump pulleys including part numbers 43034, 43037, 45005, 45006 and 45010 which cover many popular Chrysler and GM applications.



You Can Trust NAPA

NAPA's offers over 800 SKUs covering over 250 million vehicles in the U.S. and Canada. With years of innovation and experience built in, NAPA products are trusted by professional technicians and represent the highest level of quality, durability, fit, form and function available today. Feel confident every time you install NAPA Tru-Flow Water Pumps.

- *New pumps manufactured to ISO TS16949 standards*
- *100% fully tested unitized bearings/seals*
- *Computerized machined surfaces for proper fit/sealing*
- *Precisely balanced impeller for OE Fit/Function*
- *Quality packaging ensures intact delivery of all components*
- *100% inline quality tested*

Get a Grip on Water Pump Replacement

Stop Doing It the Hard Way



Shown here is the result of an attempt to secure the water pump pulley with a pipe wrench. Despite the use of duct tape, the wrench has damaged the pulley's mating surface, destroying the water pump.

NAPA Tru-Flow™ Water Pump Pulley Spanner Wrench Applications

Part #	Year	Make	Model	Engine
45005/45006/45010	2004-2007	Buick	Rainier	V-8 5.3L
45005/45010	2002-2011	Cadillac	Escalade	V-8 5.3L, 6.0L, 6.0L Electric Assist, 6.2L
45005/45010	2002-2011	Chevrolet	Avalanche	V-8 5.3L, 6.0L, 6.0L Electric Assist, 6.2L
45005/45006/45010	2003-2011	Chevrolet	Express	V-8 4.8L, 5.3L, 6.0L, 6.0L CNG, 6.0L LPG
45005/45010	1999-2011	Chevrolet	Silverado Series Pickup	V-8 4.8L, 5.3L, 6.0L, 6.0L Elec Assist, 6.2L
45005/45006	2003-2006	Chevrolet	SSR	V-8 5.3L, 6.0L
45005/45010	2000-2011	Chevrolet	Suburban	V-8 5.3L, 6.0L
45005/45010	2000-2011	Chevrolet	Tahoe	V-8 4.8L, 5.3L, 6.0L Electric Assist, 6.2L
45005/45006/45010	2003-2009	Chevrolet	Trailblazer	V-8 5.3L, 6.0L
45010	2009-2011	Chevrolet	Colorado	V-8 5.3L
43034/43037	1992-2003	Dodge	B Series Van	V-6 3.9L, 5.2L, 5.9L
43034/43037	1992-1993	Dodge	D & W Series Pickup	V-6 3.9L, 5.2L, 5.9L
43034	1998-2003	Dodge	Durango	V-6 3.9L, 5.2L, 5.9L
43034/43037	1992-2003	Dodge	Dakota	V-6 3.9L, 5.2L, 5.9L
43034	1994-2003	Dodge	Ram Series Pickup	V-6 3.9L, 5.2L, 5.9L
43034/43037	1992-1993	Dodge	Ramcharger	V-8 5.2L, 5.9L
45005/45006/45010	2003-2009	GMC	Envoy	V-8 5.3L
45005/45006/45010	2003-2011	GMC	Savana	V-8 4.8L, 5.3L, 6.0L, 6.0L CNG, 6.0L LPG
45005/45010	1999-2011	GMC	Sierra Series Pickup	V-8 4.8L, 5.3L, 6.0L, 6.0L Electric Assist, 6.2L
45005/45011	2000-2011	GMC	Yukon	V-8 4.8L, 5.3L, 6.0L, 6.0L Electric Assist, 6.2L
45010	2009-2011	GMC	Canyon	V-8 5.3L
45005/45010	2003-2010	Hummer	H2	V-8 6.0L, 6.2L
45010	2008-2010	Hummer	H3	V-8 5.3L
45010	2009-2010	Hummer	H3T	V-8 5.3L
45005/45006	2003-2006	Isuzu	Ascender	V-8 5.3L
43034	1993-1998	Jeep	Grand Cherokee	V-8 5.2L, 5.9L
45005/45010	2005-2009	Saab	9-7X	V-8 5.3L, 6.0L
45005	2009	Workhorse	MetroStar	V-8 4.8L
45005	2004-2006	Workhorse	P Series/P Series Chassis	GM V-8 4.8L, 6.0L
45005	2007-2010	Workhorse	W42/W42 Chassis	GM V-8 4.8L, 6.0L

Above is general application data, always verify with catalog application data for specific part number.



For more information about the NAPA Tru-Flow™ Water Pump Pulley Spanner Wrench, contact your NAPA Heating/Cooling Sales Representative.

