



NAPA Tech TIPS

SUPPORTING TODAY'S PROFESSIONAL TECHNICIAN

Distributor Replaced: Check Engine Light Still On

Application:

Most OBDII equipped vehicles (1995 and newer).

Problem:

Check engine light still on after distributor replacement.

Cause:

Original trouble code was not cleared from the computer.

Solution:

On some vehicles, permanent stored trouble codes must be manually cleared. After distributor replacement, if codes remain (check engine light still on), they must be erased using a suitable scan tool. Refer to your vehicle's service manual for proper procedures.

