



Tech TIPS

SUPPORTING TODAY'S PROFESSIONAL TECHNICIAN

Introducing GM Flash Technology

Application:

All 1996 and newer GM vehicles with FLASH reprogramming ECCs.

Problem:

Relearn procedures specific to the vehicle application **MUST** be followed after installing a reprogrammed ECC. Several relearn procedures may apply to one vehicle (see IMPORTANT NOTE below).

Solution:

Refer to the Tech Tips listed below for the applicable relearn procedure(s):

**Relearn
Procedures**

- PASSLOCK (Anti-Theft) TT 70-77-0001N
- IPC (Instrument Panel Cluster) TT 70-77-0002NJ
- CKP (Crankshaft Variation Relearn Procedure) TT 70-77-0003N
- TDC (Top Dead Center Offset Procedure, Diesel only) TT 70-77-0004N
- SATURN Crankshaft Position Relearn TT 70-77-0005N
- 2000-01 Cadillacs on-board procedure TT 70-77-0006N

**Important
Note:**

Refer to your vehicle's service manual for detailed relearn procedures specific to your application.