

Part Number	Description	2019 List
ZS1 CYLINDERREFURB	CYLINDER REFURB	\$ 195.00
ZS1 FLOWTEST	FLOW TEST	\$ 100.00
ZS1 HYDROTEST	HYDRO TEST	\$ 68.00
ZS1 ICMTX-R BATCOV	Replace ICMTX or TXR Battery Cover	\$ 58.00
ZS1 ICMTX-R CIR BD	Repair ICMTX or TXR Circuit Board	\$ 223.00
ZS1 ICMTX-R LCD	Repair ICMTX or TXR LCD	\$ 307.00
ZS1 ICMTX-R MAINCB	Replace ICMTX or TXR Main Circuit BD	\$ 508.00
ZS1 ICMTX-R TRANSD	Replace ICMTX or TXR Pressure Transducer	\$ 335.00
ZS1 SCBA INSPECT	SCBA INSPECTION ONLY	\$ 142.00
ZS1AH2G1UPG	Airhawk II G1 Regulator Upgrade	\$ 184.00
ZS1ICMTX-R RADIOCB	Replace ICMTX or TXR Radio Cir Board	\$ 514.00
ZS1ICMTX-R TOPCASE	Replace ICMTX or TXR Broken Top Case	\$ 274.00
ZS1ICMTXRFUBASE750	Repl ICMTXR blown750ampFuse-Base Station	\$ 184.00
ZS1ICMTX-RINSPNOWK	Rep ICMTX/TXR Inspect-incld cal&no work	\$ 142.00
ZS1ICMTX-RLOWRCASE	Replace ICMTX or TXR Broken Lower Case	\$ 402.00
ZS1ICMTX-RTAGCLEAR	Repair ICMTX/TXR Tag Clear from12-24 Hrs	\$ 117.00

*All other repairs to SCBA products not covered by a flat rate fee above will be subject to time and material billing for which MSA Service will supply an estimate / quote. If warranty conditions do not apply or if you choose not to proceed with repairs upon receiving the estimate / quote, then a minimum service / inspection fee of \$142.00 dollars will apply.