

P/N	Description	2021 List Price	Unit
ZS34BEXTR	EV6000 Basic to Extreme Upgrade	\$ 1,274.00	CAD
ZS34BEXTRLRF	EV6000 Basic to Extreme w/ LRF Upgrade	\$ 1,478.00	CAD
ZS34BFLSHRF	EV6000 Basic to Plus w/LRF Upgrade	\$ 944.00	CAD
ZS34BFLSH	EV6000 Basic toPlus w/Flashlight Upgrade	\$ 1,069.00	CAD
ZS34P2EXT	EV6000 Plus to Extreme	\$ 1,398.00	CAD
ZS34P2EXTLRF	EV6000 Plus to Extreme w/LRF Upgrade	\$ 1,478.00	CAD
Z3440101	PG34 SERVICE TIME	\$ 195.00	CAD
ZS34CHARGER	Repair TIC Truck Charger	\$ 330.00	CAD
ZS34 INSP TIC	TIC EVALUATION & INSPECTION FEE	\$ 250.00	CAD
ZS34 INSP ACC	ACCESSORY EVALUATION & INSPECTION FEE	\$ 185.00	CAD

Estimates will be provided for Thermal Imaging Camera repairs if flat fee does not apply.

Declined repairs will subject to Inspection fees mentioned above.

All repairs that are not able to be completed at a MSA Canada Service center will be forwarded to MSA USA for completion.