

---

**PrimaX® Gas Monitor – Order Form**

---

**PrimaX I Gas Monitor, UL Approved**



10112505	Oxygen, 0-25%
10112300	Carbon monoxide CO, 200 ppm
10112336	Hydrogen sulfide H2S, 50 ppm
10112438	Ammonia NH3, 100 ppm
10112439	Ammonia NH3, 500 ppm
10112282	Chlorine Cl2, 50 ppm
10112596	Sulfur dioxide SO2, 50 ppm
10112372	Hydrogen cyanide HCN, 30 ppm
10112354	Hydrogen chloride HCl, 30 ppm
10112318	Hydrogen H2, 1000 ppm
10112469	Nitric oxide NO, 100 ppm
10112487	Nitrogen dioxide NO2, 10 ppm
10112506	Oxygen, 0-25%, HART
10112301	Carbon monoxide, 200 ppm, HART
10112337	Hydrogen sulfide H2S, 50 ppm, HART
10112440	Ammonia NH3, 100 ppm, HART
10112441	Ammonia NH3, 500 ppm, HART
10112283	Chlorine Cl2, 50 ppm, HART
10112597	Sulfur dioxide SO2, 50 ppm, HART
10112373	Hydrogen cyanide HCN, 30 ppm, HART
10112355	Hydrogen chloride HCl, 30 ppm, HART
10112319	Hydrogen H2, 1000 ppm, HART
10112470	Nitric oxide NO, 100 ppm, HART
10112488	Nitrogen dioxide NO2, 10 ppm, HART

**PrimaX P Gas Monitor, UL Approved**



10112419	Methane, 0-100% LEL
10112564	Propane, 0-100% LEL
10112511	Oxygen, 0-25%
10112306	Carbon monoxide, 200 ppm
10112342	Hydrogen sulfide H2S, 50 ppm
10112450	Ammonia NH3, 100 ppm
10112451	Ammonia NH3, 500 ppm
10112288	Chlorine Cl2, 50 ppm
10112622	Sulfur dioxide SO2, 50 ppm
10112378	Hydrogen cyanide HCN, 30 ppm
10112360	Hydrogen chloride HCl, 30 ppm
10112324	Hydrogen H2, 1000 ppm
10112475	Nitric oxide NO, 100 ppm
10112493	Nitrogen dioxide NO2, 10 ppm
10112420	Methane, 0-100% LEL, HART and relays
10112565	Propane, 0-100% LEL, HART and relays
10112512	Oxygen, 0-25%, HART and relays
10112307	Carbon monoxide CO, 200 ppm, HART and relays
10112343	Hydrogen sulfide H2S, 50 ppm, HART and relays
10112452	Ammonia NH3, 100 ppm, HART and relays
10112453	Ammonia NH3, 500 ppm, HART and relays
10112289	Chlorine Cl2, 50 ppm, HART and relays
10112623	Sulfur dioxide SO2, 50 ppm, HART and relays
10112379	Hydrogen cyanide HCN, 30 ppm, HART and relays
10112361	Hydrogen chloride HCl, 30 ppm, HART and relays
10112325	Hydrogen H2, 1000 ppm, HART and relays
10112476	Nitric oxide NO, 100 ppm, HART and relays
10112494	Nitrogen dioxide NO2, 10 ppm, HART and relays

**PrimaX Gas Monitor Accessories**

10113033	Sensor Guard
10113031	Flow Adapter
10112790	Duct Mount Kit
10113132	Pipe-mounting Kit
10113034	Sensor Tag
10113035	Sunshield
101127889	Calibration Cap
10113036	Universal HART Cable