

28446 Axle repair kit for 2002-1946 GM $\frac{1}{2}$, $\frac{3}{4}$, 1, 1 $\frac{1}{2}$ ton trucks


TT 08-004

April 2008

Tech tip

Avoid reoccurring rear axle repairs by installing an SKF Speedi-Sleeve and a new seal, both included in one kit part number.

The 28446 repair kit includes a 28426 seal and the proven 99282 repair sleeve to prevent seal leakage due to a polished or worn seal surface, commonly found on these applications.



Application Details

2002 - 1971	$\frac{1}{2}$ Ton G20, G25, G30, G35, w/10.50" Ring Gear
1972 - 1946	$\frac{3}{4}$ Ton 2500 C, K, R & V Series, Exc. Spicer Axles
2002 - 1973	$\frac{3}{4}$ Ton 2500 C, K, R & V Series, w/ 10.50" Ring Gear
1972 - 1946	1 Ton, H052 & H072 Axles
2002 - 1973	1 Ton 3500 C, K, P, R & V Series, w/ 10.50" Ring Gear, Exc. Dana & 4 Wheel Disc Brakes.
1987 - 1984	1 $\frac{1}{2}$ Ton Spicer 70 Axles.

SKF Vehicle Service Market North America
890 N. State St., Suite 200
Elgin, IL 60123
1-800-882-0008



Install confidence
www.vsm.skf.com