

8055N

Freightliner
2008-2019
M2 & M2-112V
Cummins ISB

KYSOR-STYLE FAN CLUTCHES

NEW



REPLACES
HORTON® 991455,
981455, 99A9649



OURS LOOKS DIFFERENT BECAUSE IT IS DIFFERENT.

Direct replacement/upgrade for Horton® 991455 Fan Clutches

The superior design of the 8055N makes for easier and more affordable long-term maintenance. Converting your fan clutch upgrades it from a medium duty fan clutch to a heavy duty fan clutch. Our model is capable of handling a larger fan and will last longer than the competition.

**This fan clutch requires air to disengage, so reversing the solenoid is required.
If solenoid is not reversible, you must purchase Part #3282.**



Learn more at
kitmastersuniversity.com

KIT MASTERS
FAN CLUTCH EXPERTS

825 1st St. NE, Perham, MN • 800-810-9110
www.KitMasters.com

