



Rectangular Bases with 1 Pc Top Assembly Instructions

Before attaching bases, please take appropriate precautions to protect the table top.

Components:

- 2 Rectangular Bases
- 1 Piece Rectangular Conference Top
- 5/8" #8 Screw (Qty 24 per Base; 24 per Stretcher Rail)
- Adjustable Glides (Qty 2 per Base)
- L Brackets (Qty 6 per Base; 6 per Stretcher Rail)
- Stretcher Rails (Set of 2 for 1 Pc Top)

Instructions

- 1 Insert adjustable glides into bottom of bases.
- 2 Attach (3) L-Brackets to either side of the base. Space the outer brackets approx. 2" from the edge. Keep top edge of bracket flush with top edge of base. Repeat for the other base.
- 3 Attach (6) L brackets to the stretcher rail per the picture. Keep the top edge of the brackets flush with the edge of the stretcher. Repeat for the other stretcher.
- 4 Fasten stretchers flush with the edge of the bases.
- 5 With the top upside-down, position the base 19" from the edge of the top (96" long top) and centered front to back. (7" from edge for 42" deep top)
- 6 Once in position, attach the L-Brackets on the base assembly to the top.
- 7 Now, you're ready to turn the table right side up, level the table with the adjustable glides.

Install L-Brackets approx. 2" from the edge & flush with the top.

2

Install L-Brackets equally spaced & flush with the top.

3

Install L-Brackets centered & flush with the ends.

4

Flush

5

