


Stahl Mobile Pedestal Assembly

STEP 1

COMPLETED

(A) Castor



(B) Self-tapping screw

