

## SERVICE AND APPLICATION NOTES

# Mini-Split Electrical Service Disconnect

### Affected Product

The Lennox Indoor Mini-Splits models affected are MWMA, MWMB, M22, M33, MMD, MCF, MWCA and MWHA.

### Issue


When there is a City, County or State electrical code that requires a electrical service disconnect to be installed for the indoor mini-split unit.

The contractor will provide the necessary parts required which typically includes a double pole single throw (DPST) switch; electrical box and 14-3 or 16-3 stranded wire with ground cable.

The communication wire cannot be cut or spliced in this application. Location of box is at the discretion of the installing contractor. We suggest the disconnect could be mounted right under the indoor unit or in the wall as local code requires.

### Procedure:

Below is an illustration on how the disconnect should be installed.



**Figure 1. Disconnect Installation**