

Material	Description	Jan 2024 List Price
ZS1 CYLINDERREFURB	CYLINDER REFURB	\$ 274.00
ZS1 FLOWTEST	FLOW TEST	\$ 141.00
ZS1 HYDROTEST	HYDRO TEST	\$ 94.75
ZS1 SCBA INSPECT	SCBA INSPECTION ONLY	\$ 225.00
ZS1AH2G1UPG	Airhawk II G1 Regulator Upgrade	\$ 254.00
ZS1BHCONNREP	G1 PWR MOD BULKHEAD &BATTERY CONN REPAIR	\$ 404.00
ZS1NOPASS	G1 no pass update	\$ 502.00

*All other repairs to SCBA products not covered by a flat rate fee above will be subject to time and material billing for which MSA Service will supply an estimate / quote. If warranty conditions do not apply or if you choose not to proceed with repairs upon receiving the estimate / quote, then a minimum service / inspection fee of \$225.00 dollars will apply.