

Material	Description	4/15/22 List
ZS34 INSP ACC	ACCESSORY EVALUATION & INSPECTION FEE	\$ 190.00
ZS34 INSP TIC	TIC EVALUATION & INSPECTION FEE	\$ 283.00
ZS34BEXTR	EV6000 Basic to Extreme Upgrade	\$ 1,255.00
ZS34BEXTRLRF	EV6000 Basic to Extreme w/ LRF Upgrade	\$ 1,807.00
ZS34BFLSH	EV6000 Basic to Plus w/Flashlight Upgrade	\$ 1,054.00
ZS34BFLSHRF	EV6000 Basic to Plus w/LRF Upgrade	\$ 1,296.00
ZS34CHARGER	Repair û TIC Truck Charger	\$ 325.00
ZS34P2EXT	EV6000 Plus to Extreme	\$ 1,378.00
ZS34P2EXTLRF	EV6000 Plus to Extreme w/LRF Upgrade	\$ 1,807.00

Repairs to Thermal imaging products are subject to time and material billing for which MSA Service will supply an estimate / quote. If warranty conditions do not apply or if you choose not to proceed with repairs upon receiving the estimate / quote, then minimum service / inspection fees of \$190.00 dollars for accessories and \$283.00 dollars for TIC's will apply.