

Material	Description	Jan 2024 Price
Z3440010	REPAIR & SERVICE, PER HOUR LABOR RATE	\$225.00
Z3440042	SHUTTER REPLACEMENT PACKAGE	\$467.00
ZS34 INSP ACC	ACCESSORY EVALUATION & INSPECTION FEE	\$225.00
ZS34 INSP TIC	TIC EVALUATION & INSPECTION FEE	\$320.00
ZS34BEXTR	EV6000 Basic to Extreme Upgrade	\$1,400.00
ZS34CHARGER	Repair – TIC Truck Charger	\$364.00
ZS34P2EXT	EV6000 Plus to Extreme	\$1,538.00

Repairs to Thermal imaging products are subject to time and material billing for which MSA Service will supply an estimate / quote. If warranty conditions do not apply or if you choose not to proceed with repairs upon receiving the estimate / quote, then minimum service / inspection fees of \$225.00 dollars for accessories and \$320.00 dollars for TIC's will apply.