

January 1, 2024 - Thermal Imaging Camera		
PART NUMBER	DESCRIPTION	LIST
Z3440010 OR Z3440101	PG 34 SERVICE TIME	\$250.00
ZS34 INSP ACC	ACCESSORY EVALUATION & INSPECTION FEE	\$245.00
ZS34 INSP TIC	TIC EVALUATION & INSPECTION FEE	\$326.00
ZS34CHARGER	Repair TIC Truck Charger	\$435.00
ZS34BEXTR	EV6000 Basic to Extreme Upgrade	\$ 1,680.00
ZS34P2EXT	EV6000 Plus to Extreme	\$ 1,846.00

Estimates will be provided for Thermal Imaging Camera repairs if flat fee does not apply.

Declined repairs will subject to Inspection fees mentioned above.

All repairs that are not able to be completed at a MSA Canada Service center will be forwarded to MSA USA for completion.