MSA ALTAIR® 2X Gas Detectors

Introduction





UNIQUE PULSE CHECK

AUTOMATICALLY CHECKS SENSOR RESPONSE AND CORRECTS FOR SENSOR INTEGRITY. (ALTAIR 2XP DETECTOR ONLY)


95 DB ALARM -

WITH RED LED INDICATORS AND VIBRATING ALARM



A CHECK MARK AND GREEN LED INDICATOR MEANS YOU ARE BUMPED AND READY TO GO

DURABILITY — IP 67 DESIGN AND INTRINSICALLY SAFE CONSTRUCTION SURVIVES 25 FT DROP TEST





A SIMPLE EXHALED
BREATH VERIFIES THAT
SENSOR FLOW PATH IS
CLEAR TO ENSURE THAT
GAS REACHES THE SENSOR.
(2XP ONLY)

EASY ONE-BUTTON, GLOVED-HAND OPERATION

END OF SENSOR LIFE INDICATOR



LARGE, HIGH CONTRAST DISPLAY SHOWS PPM AND VISUAL SENSOR STATUS

DURABLE, RUBBERIZED HOUSING FOR SECURE GRIP



RED LED INDICATORS
SHOW THAT THE
INSTRUMENT HAS NOT
BEEN BUMP TESTED













GLOWING VERSION FOR LOW LIGHT APPLICATIONS AND EASIER FLEET MANAGEMENT OF MULTIPLE DETECTOR SETTINGS.



Why ALTAIR 2X Detectors?

| FEATURES | BENEFITS | |
|--|---|--|
| VARIETY OF OPTIONS | ALTAIR 2X Single-Gas Detectors with XCell Sensors ALTAIR 2XP Single-Gas Detector with XCell Pulse Technology ALTAIR 2XT Two-Tox Gas Detectors with XCell Two-Tox Sensors | |
| LOW COST OF OWNERSHIP | Fastest sensor response times, lowest calibration gas flow rate on the market 4-year expected instrument & sensor life 3-year warranty on instrument & most sensors (2 years on Cl₂, NH₃) Stand-alone bump tests reduce maintenance, increase productivity (ALTAIR 2XP Detector only) 1 device can monitor 2 gases (ALTAIR 2XT Detector only) | |
| INCREASED SAFETY AWARENESS & REAL-TIME COMPLIANCE | ,,,,,, | |
| FULL-TIME TRACEABILITY | Records 300+ alarm events and 850+ hours of periodic data, including bump and calibration records Compatible with MSA GALAXY® GX2 Automated Test System and MSA Link Pro Software | |
| RUGGED DURABILITY | Tough over-molded rubber armor Survives multiple 25-ft drops onto concrete Agency-certified dust- and water-tight IP67 and intrinsically-safe construction | |
| EASY TO USE | 1-button, gloved hand operation Large LCD, characters, and status icons Onscreen step-by-step user instructions for stand-alone bump test (ALTAIR 2XP Detector only) 10s backlight with adjustable timeout | |

Markets

- Drilling
- Refining
- Pipeline
- Chemical Processing
- Contractors
- Metals Processing
- General Industrial
- Fire Service

Complimentary Training

Care and use videos are available at no cost at the MSA-U® Training Center: www.MSAsafety.com/msau



Key Products

| DESCRIPTION | CHARCOAL | GLOW-IN-THE-DARK |
|---|----------|------------------|
| ALTAIR 2XP Gas Detector: H ₂ S-Pulse | 10153984 | 10154188 |
| ALTAIR 2XT Gas Detector: Two-Tox CO/H ₂ S | 10154040 | 10154181 |
| ALTAIR 2XT Gas Detector: Two-Tox SO ₂ /H ₂ S-LC | 10153985 | 10154190 |
| ALTAIR 2X Gas Detector: CO | 10153986 | 10154185 |
| ALTAIR 2X Gas Detector: SO ₂ | 10154077 | 10154191 |

For More Information

- MSAsafety.com/ALTAIR2X
- 1-800-MSA-2222
- $\bullet\ in fo@MSA safety.com$

- facebook.com/MSAsafety
- twitter.com/MSAsafety
- youtube.com/MSAsafety

Note: This bulletin contains only a general description of the products shown. While uses and performance capabilities are described, under no circumstances shall the products be used by untrained or unqualified individuals and not until the product instructions including any warnings or cautions provided have been thoroughly read and understood. Only they contain the complete and detailed information concerning proper use and care of these products.

ID 0802-97-MC / Mar 2016 © MSA 2016 Printed in U.S.A. MSA – The Safety Company 1000 Cranberry Woods Drive

1000 Cranberry Woods Drive Cranberry Township, PA 16066 USA Phone 724-776-8600

www.MSAsafety.com

U.S. Customer Service Center Phone 1-800-MSA-2222

Phone 1-800-MSA-2222 Fax 1-800-967-0398

MSA Canada Phone

Phone 1-800-672-2222 Fax 1-800-967-0398

MSA Mexico

Phone 01 800 672 7222 Fax 52 - 44 2227 3943