

# **OptimAir® Mask-Mounted PAPR      Kit No. 10095164**

---

## **replacing cable assembly**

### **REMOVE CABLE ASSEMBLY**

1. Unthread cable assembly ring from motor-blower and cable assembly ring from battery pack.
2. Pull cable plug from motor-blower and battery pack.

### **INSTALL NEW CABLE ASSEMBLY**

1. Align key on cable plug with slot in female connector on the battery pack and repeat procedure in motor-blower.
2. Push the plug into the female connector and turn the ring to secure.
3. Turn switch located on battery pack to the ON position to ensure motor-blower operates properly.

For More Information, call 1-800-MSA-2222 or Visit Our Website at [www.MSAnet.com](http://www.MSAnet.com)



*The Safety Company*  
MSA 901 (L) Rev. 0

**MINE SAFETY APPLIANCES COMPANY  
PITTSBURGH, PENNSYLVANIA, U.S.A. 15230**

© MSA 2009

Print. Spec. 10000005196(A)    Mat. 10095201  
Doc. 10095201