

# FireHawk® M7 Air Mask

Ordering Selection Matrix (NIOSH 42 CFR Part 84)



A	B	C	D	E	F	G	H	I	J	K	L	M
Air Mask Pressure	Carrier/Harness Assembly	Lumbar Pad/Rescue Belt	Cylinder	MMR Type	Emergency Breathing Support	Facepiece	Nosecup	Head Harness	Electronic Communications	Pressure Gauge/Integrated PASS	Heads-Up Display	Case
L 2216	<b>A</b> Single Pull without chest strap  <b>B</b> Single Pull with chest strap  <b>C</b> Double Pull without chest strap  <b>D</b> Double Pull with chest strap  <i>Options A &amp; B can only be chosen if a rescue belt is selected.</i>	<b>0</b> None  <b>1</b> Swiveling Lumbar Pad  <b>G</b> Rescue Belt II, w/hook, 50'  <b>H</b> Rescue Belt II, w/carabiner, 50'  <b>J</b> Rescue Belt II, w/hook, FireTech rope, 50'  <b>K</b> Rescue Belt II, w/carabiner, FireTech rope, 50'  <i>If choosing a rescue belt, the carrier/harness assembly must be a single pull (options A or B).</i>	<b>0</b> None  <b>1</b> 3AL Aluminum with air  <b>3</b> 30' Carbon with air  <b>4</b> 3AL Aluminum less air  <b>6</b> 30' Carbon less air  <b>0</b> None  <b>1</b> 30+ Carbon with air  <b>2</b> 30+ Carbon less air  <b>0</b> None  <b>1</b> 30' Carbon with air  <b>2</b> 45' Carbon with air  <b>3</b> 45' Carbon H-45 SL  <b>4</b> 60' Carbon with air  <b>5</b> 30' Carbon less air  <b>6</b> 45' Carbon less air  <b>7</b> 45' Carbon H-45 SL less air  <b>8</b> 60' Carbon less air	<b>A</b> CBRN Firehawk STC, threaded  <b>B</b> CBRN Firehawk STC, QC  <b>C</b> CBRN Firehawk PTC, threaded  <b>D</b> CBRN Firehawk PTC, QC  <i>If choosing an ExtendAire I option, the MMR type must be a QC (option B or D).</i>	<b>0</b> None  <b>1</b> Quick-Fill  <b>2</b> ExtendAire I  <b>3</b> Quick-Fill and ExtendAire I  <b>A</b> ExtendAire II  <b>B</b> ExtendAire II with Quick-Fill  <b>C</b> ExtendAire I & II  <b>D</b> ExtendAire I & II with Quick-Fill  <i>If choosing an Air Mask Pressure M, M is not compatible with Quick-Fill.</i>	<b>A</b> None  <b>B</b> Hycar Small  <b>C</b> Hycar Medium  <b>D</b> Hycar Large	<b>0</b> None  <b>1</b> Medium  <b>2</b> Large	<b>0</b> None  <b>2</b> Speed-ON less neck strap  <b>4</b> Speed-ON with neck strap	<b>A</b> None  <b>B</b> ClearCommand Ready with bracket  <b>C</b> ClearCommand Amp  <b>D</b> ClearCommand Amp/RI	<b>1</b> Pressure Gauge and HUD Transmitter  <b>A</b> PASS with thermal alarm activated  <b>B</b> PASS without thermal alarm activated  <i>If choosing a pressure Gauge and HUD Transmitter, the Heads-up Display type must be M7 HUD (Option A).</i>	<b>A</b> M7 HUD  <b>B</b> M7 I-HUD	<b>0</b> None  <b>1</b> Hard Case  <b>2</b> Soft Case
M 3000												
H 4500												

Column: A B C D E F G H I J K L M

B-M7

PART NUMBER

QUANTITY