



The Safety Company

Mine Safety Appliances Company • John T. Ryan Memorial Lab  
1100 Cranberry Woods Drive, Cranberry Township, PA 16066

MSA Engineering Self Certification of Standard Compliance  
IAC-03-005-Z04

Statement of Compliance: This Frame, Headgear, and Chin Protector meets the requirements of ANSI/ISEA Z87.1-2010 for Ignition Resistance.

Tested part number(s) or IAC No.:	"Sold as" part number(s)/Market:
10116538, 10121266, 10121267, 10121268, 10124426, 10116627, 10116628, 10115827, 10115828, 10127061, 10127062	10116538, 10121266, 10121267, 10121268, 10124426, 10116627, 10116628, 10115827, 10115828, 10127061, 10127062

Test Facility & Document #:  
Intertek  
G100617274CRT-006  
G101105154CRT-006

SCP Project #  
MSA13-08A

PERFORMANCE DETAILS

(May format as needed)

ANSI/ISEA Z87.1-2010 Standard Referenced Section	Results	Pass / Fail
Section 5. General Requirements		
<ul style="list-style-type: none"> <li>5.2.3 Ignition</li> </ul>	No externally exposed material (exclusive of textiles and elastic bands) of the protector ignites or continues to glow once the heated rod is removed.	PASS

For additional information about this product(s), please contact MSA Customer Service at 1-800-MSA-2222 (for industrial products) or Safety Works Customer Service at 1-800-969-7562 (for retail products). When requesting information, please reference "sold as" part number(s).

Quality Assurance:   
JAMES WONDERLING

Date: