## ANSI/ISEA Z89.1-2014

# American National Standard for Industrial Head Protection



On May 15, 2014, American National Standards Institute (ANSI) issued approval for ANSI/ISEA Z89.1-2014, American National Standard for Industrial Head Protection. This standard was prepared by members of ISEA's Head Protection Group as a revision to the 2009 edition, and approved by a consensus review panel comprised of technical experts, unions, construction industry and other user groups, test labs, and certification and government agencies.

### What is ANSI/ISEA Z89.1-2014?

ANSI/ISEA Z89.1-2014 Standard (the "Standard") provides industrial hard hat performance and testing requirements. The Standard establishes types and classes of protective helmets to provide employers with hard hat options that provide appropriate protection for hazards present in a given workplace. The Standard addresses the following:

- Specifications for helmets by Type (based upon impact force location) and Class (based upon electrical insulation);
- Impact occupational settings under normal temperature conditions and, optionally, pre-conditioning to higher and lower temperatures;
- · Safety recommendations for hard hats worn in the reversed position;
- · Requirements for high-visibility helmets;
- · Test methods for evaluating all requirements; and
- User cautions and recommendations regarding helmet care.

### Why was a new Standard created?

Voluntary industry consensus standards recognized by ANSI are required to be reviewed every five years; the previous edition was ANSI/ISEA Z89.1-2009.

### What updates have been made to ANSI/ISEA Z89.1-2014?

Core performance requirements remain unchanged; however, three important updates to ANSI/ISEA Z89.1-2014 are listed here:

### **1** Section 5: Accessories and Replacement Components

While already a Z87 face protection requirement, the Standard 2009 version indicated that accessories or components installed onto hard hats cannot cause the helmet to fail. The 2014 Standard update provides additional language further supporting the premise that accessory/component manufacturers are responsible for proving that their products do not cause helmets to fail:

"The entity claiming that an accessory or replacement component, when installed, will not cause the helmet to fail the requirements of this Standard, and is responsible for providing justification upon request."

### 2 Section 6: Instructions and Markings

Clarification language was added to this section to help customers understand that "useful service life" for helmets is not required by the Standard, although helmet manufacturers may choose to include it.

"NOTE: Useful service life guidelines are intended to provide the user with information that certain conditions may affect a specific helmet's continued protection over time. A specific service life, defined in terms of number of years, is not required though individual manufacturers may choose to include such information for their respective helmets."

### **3** Section 7.3.3 Higher Temperatures

The revision enables additional protection in response to the needs of users who may work within hot environments. 2009 Standard hot temperature conditioning was  $48.8^{\circ}\text{C} \pm 2^{\circ}\text{C}$  ( $120^{\circ}\text{F} \pm 3.6^{\circ}\text{F}$ ). Optional preconditioning at higher temperatures of  $60^{\circ}\text{C} \pm 2^{\circ}\text{C}$  ( $140^{\circ}\text{F} \pm 3.6^{\circ}\text{F}$ ) has been added to the 2014 version. If a helmet has been preconditioned to  $60^{\circ}\text{C} \pm 2^{\circ}\text{C}$  ( $140^{\circ}\text{F} \pm 3.6^{\circ}\text{F}$ ), the helmet will be marked as HT. In addition, new updates allow for flexibility and inclusion of emerging and current best manufacturing materials for higher temperature protection.

**Caveat:** the Standard does not address pre-conditioning that could be needed for temperature and radiant heat extremes. To ensure that you have the proper head protection level needed for your specific heat application, check with the manufacturer for stated usage of any helmet.

### The new Standard and Product Compliance

ANSI/ISEA Z89.1-2014 does not require users to discontinue using products labeled as compliant with the 2009 Standard. However, if your occupation requires compliance with new optional certifications such as pre-conditioning at higher temperature, older product will *not* be marked and may not be compliant. When in doubt, check with OSHA for specific requirements.

### Conclusion

Worker safety is always the highest job site priority, and head protection is an essential element in providing workers with protection from falling debris, low hanging objects and electrical hazards. A Standard-compliant, properly marked hard hat should be worn in all situations where head protection hazards exist.

A copy of ANSI/ISEA Z89.1-2014 can be purchased from International Safety Equipment Association's (ISEA); visit www.safetyequipment.org for details.



### MSA—The Safety Company

Our business is safety. We've been the world's leading manufacturer of high-quality safety products since 1914. MSA products may be simple to use and maintain, but they're also highly-sophisticated devices and protective gear — the result of countless R&D hours, relentless testing, and an unwavering commitment to quality that saves lives and protects thousands of men and women each and every day. Many of our most popular products integrate multiple combinations of advanced materials, electronics and mechanical systems to ensure that users around the world remain protected within even the most hazardous of situations.

### Our Mission

MSA's mission is to see to it that men and women may work in safety and that they, their families and their communities may live in health throughout the world.

MSA: Because every life has a purpose.

**Note:** This bulletin contains only a general description of the products shown. While uses and performance capabilities are described, under no circumstances shall the products be used by untrained or unqualified individuals and not until the product instructions including any warnings or cautions provided have been thoroughly read and understood. Only they contain the complete and detailed information concerning proper use and care of these products.

### ID 0600-66-MC / August 2014

© MSA 2014 Printed in U.S.A. Subject to changes without notice

### MSA – The Safety Company

1000 Cranberry Woods Drive Cranberry Township, PA 16066 USA Phone 724-776-8600 www.MSAsafety.com

### U.S. Customer Service Center

Phone 1-800-MSA-2222 Fax 1-800-967-0398

#### Pacific Asia Region MSA Singapore

MSA S.E Asia Pte Ltd 35 Marsiling Industrial Estate Road 3, #04-01, Singapore 739257 Phone: +65 6350 4500 Fax: +65 6350 4505

### MSA Australia

Phone: 1300 728 672 / +61 02 9688 0333 Fax: +61 2 9896 1835

### MSA Indonesia

Phone: +62 21 6409 000 Fax: +62 21 641 2831

### MSA Malaysia

Phone: +603 8724 8208/9208 Fax: +603 8724 2208

#### MSA New Zealand Customer Service Phone: 0800 441 335

MSA Philippines

Phone: +63 9209 742 191

MSA Thailand

Phone: +66 2617 8211 Fax: +66 2617 8214