

ZS23 APTURA LT 30	Repair Aptura LT 30' (13'-30')\$ or scrap	\$ 328.00
ZS23 APTURA INSP	APTURA INSPECT/TEST	\$ 142.00
ZS23 DL CBL 50'MAX	Repair Dynalock cable over 50' max \$	\$ 667.00
ZS23 DL CBL 50'MIN	Repair Dynalock cable over 50' min \$	\$ 336.00
ZS23 DL20' W/C MAX	Repair Dynalock 20' web & cable max \$	\$ 447.00
ZS23 DL20' W/C MIN	Repair Dynalock 20' web & cable min \$	\$ 252.00
ZS23 DL30/50CBLMAX	Repair Dynalock 30'&50' cable max \$	\$ 601.00
ZS23 DL30/50CBLMIN	Repair Dynalock 30'&50' cable min \$	\$ 336.00
ZS23 DV/LYNX MAX	Repair Dynevac II max \$	\$ 683.00
ZS23 DV/LYNX MIN	Repair Dynevac II min \$	\$ 368.00
ZS23 DYNEVACII CON	Dynevac II conversion	\$ 1,177.00
ZS23 INSP FEE	SRL MIN EVALUATION & INSPECTION FEE	\$ 142.00
ZS23 TRIPOD MIN	Tripod Inspection	\$ 142.00
ZS23 TRIPOD MAX	Repair Tripod max \$	\$ 240.00
ZS23 WINCH65INS	WORKMAN WINCH 65' INSPECT/TEST	\$ 226.00
ZS23 WINCH65STD	WORKMAN WINCH 65' STANDARD REPAIR	\$ 457.00
ZS23 WKMAN GLV MAX	Repair Workman SRL 30' GALV Cable Max	\$ 315.00
ZS23 WKMAN GLV MIN	Repair Workman SRL 30' GALV Cable Min	\$ 210.00
ZS23 WKMAN SST MAX	Repair Workman SRL 30' SST Cable Max	\$ 331.00
ZS23 WKMAN SST MIN	Repair Workman SRL 30' SST Cable Min	\$ 210.00
ZS23 WKMN 50GLV MN	REPAIR WORKMAN SRL 50', GALV CABLE MIN	\$ 236.00
ZS23 WKMN 50GLV MX	REPAIR WORKMAN SRL 50', GALV CABLE MAX	\$ 389.00
ZS23 WKMN 50SST MN	REPAIR WORKMAN SRL 50', SST CABLE MIN	\$ 236.00
ZS23 WKMN 50SST MX	REPAIR WORKMAN SRL 50', SST CABLE MAX	\$ 424.00
ZS23 WKMNRESCUE MN	REPAIR WORKMAN RESCUER MIN	\$ 389.00
ZS23 WKMNRESCUE MX	REPAIR WORKMAN RESCUER MAX	\$ 615.00
ZS23DVIIMAX	Repair DVII	\$ 725.00
ZS23DVIIMIN	Inspect / recertify DVII	\$ 389.00
ZS23EQUIPINSP	Fall Protection Harness Inspection	\$ 16.00

\*All Fall Protection product repairs are subject to a minimum \$142.00 dollar service fee.