

P/N	Description	2021 List Price	Unit
Z3640101	PG36 SERVICE TIME	\$ 170.00	CAD
Z-REP-PAINT-TR-HAN	REPAIR, PAINTING, TRIM, AND HANGAR	\$ 398.00	CAD
Z-REP-FRNTHLDR	Repl Cairns Front Holder - Silk/Carved	\$ 75.00	CAD
Z-REP-IMPACT	Replace Cairns Impac/Susp	\$ 174.00	CAD
Z-REP-EARLAP	Replace Earlap	\$ 162.00	CAD
ZREPTHIMPAC	Replace Leather impac cap / band	\$ 255.00	CAD
ZREPPLEARLAP	Replace nomex Earlap, Plastic	\$ 75.00	CAD
Z-REP-C893	Chinstrap QRB and PS	\$ 106.00	CAD

All MSA Fire helmets not able to be serviced at a MSA Canada Service center will be forwarded to MSA USA for servicing.

Estimates will be provided as required.

Declined repairs will be subject to a minimum \$85.00 estimate fee.