
Sound Control® SH

Ear protection that fits to a V






You asked for it. We listened. Ear protection made easy.

Gone are the days of drilling holes into your hard hat! The new slots added to the V-Gard® Full Brim Hard Hat were designed to help you accessorize with ease. Sound Control SH is a compatible ear muff that fits snugly in the new accessory slots.





Because every life has a purpose...







Sound Control SH Key Product Features

- Spring design offers low pressure and a high level of comfort
- Three distinct wearing positions for ease of use
- Excellent grip makes it easy to adjust the cups, even when wearing gloves
- Provides maximum space for the ears inside the cup
- · Soft ear cup material for extended wear
- · Easy ear cup height adjustment
- Retain the Class E dielectric rating on the V-Gard Full Brim Hard Hat

Best Line of Defense


Sound Control SH

Defense against excessive noise exposure includes proper selection of hearing protection. That's why MSA is introducing Sound Control SH. An ear muff designed to make accessorizing not only easier, but safer. We have tested and evaluated our ear muffs for quality, attenuation and effectiveness in combating workplace noise. What's more, with our ear muffs, you still retain the Class E dielectric rating on your V-Gard Full Brim Hard Hat, making compliance easy!

Ordering Information

Part Number	Description
10129327	Sound Control SH* NRR 25dB

^{*} Full Brim Hat not included



Did you know...

Noise-Related Hearing Loss: An Occupational Health Concern

One of the most prevalent occupational health concerns in the United States is noise-related hearing loss.

Approximately 30 million people per year are exposed to hazardous noise and thousands suffer from preventable hearing loss.

The effects of hearing loss can create physical and psychological stress, reduce productivity, interfere with communication and concentration, and contribute to workplace accidents and injuries by making it difficult to hear warning signals.

Note: This Bulletin contains only a general description of the products shown. While uses and performance capabilities are described, under no circumstances shall the products be used by untrained or unqualified individuals and not until the product instructions including any warnings or cautions provided have been thoroughly read and understood. Only they contain the complete and detailed information concerning proper use and care of these products.

ID 0613-58-MC / October 2012 © MSA 2012 Printed in U.S.A. MSA Corporate Center 1000 Cranberry Woods Drive Cranberry Township, PA 16066 USA Phone 724-776-8600 www.MSAsafety.com

 U.S. Customer Service Center

 Phone
 1-800-MSA-2222

 Fax
 1-800-967-0398

 MSA Canada

Phone 1-800-672-2222 Fax 1-800-967-0398

MSA Mexico Phone

Phone 01 800 672 7222 Fax 52 - 44 2227 3943 **MSA International**

 Phone
 724-776-8626

 Toll Free
 1-800-672-7777

 Fax
 724-741-1559

 Email
 msa.international@msanet.com

Offices and representatives worldwide For further information:

