## **SERVICE AND APPLICATION NOTES**

100014 09/01/2021 Reissued 05/2021

## **Lennox 90% Furnace Cabinet Plugs and Grommets**

Lennox Technical Support has been getting calls regarding grommets or plugs in the cabinet of some 90% furnace models. All 90% gas furnaces with Constant Torque and Variable Speed blower motors have a sealed burner design and do not require plugs or grommets to seal the cabinet.

The motor type is denoted by either "E" or "V" in the model number as shown in the below example:

If you have any questions, please contact Lennox Technical Support at (800)453-6669.



