



The Safety Company

Mine Safety Appliances Company • 1000 Cranberry Woods Dr. • Cranberry Twp. PA 16066

### PrimaX<sup>®</sup> IR Gas Monitor – ATO Order Form

A-PRIMAXIR	—	—	—	—	—	—	—	—
0	1	2	3	4	5	6	7	8

- 1 **Target Gas**  
14 = Methane 0-100% LEL 5.0%  
15 = Propane 0-100% LEL – 2.1%
- 2 **Approval Agency**  
F = FM
- 3 **Thread Types**  
N = NPT
- 4 **Unused**  
0 = None
- 5 **Junction Box**  
0 = None  
3 = 316 Stainless Steel Explosion-proof Box  
(Includes bracket)
- 6 **Mounting Style**  
0 = None  
1 = Sensor attached to Junction Box  
(Only available if Matrix 5 = 3)
- 7 **Future Expansion**  
0 = None
- 8 **Custom**  
0 = None  
C = Custom Operation



#### Accessories

- 10113100 Flow Cap – SS 316
- 10114373 Duct-mount Kit – SS 316
- 10114097 Environmental Guard Tether – SS 316
- 10119593 HART Junction Box – SS 316
- 10116418 Insect Guard – SS 316
- 10113481 Sunshield – SS 316
- 10111874 Calibration Cap w/display
- 10081441 Universal HART Cable
- 10122228 Blind Calibration Cap (use with HART Field Communicator)
- 10122783 Remote Cal Adapter