

Material	Description	Jan 2024 List Price
ZS07 4PT UPGRADE	UPGRADE 1 PT TO 4 PT SEQUENCER - RT/CG	\$ 2,996.00
ZS07 8PT UPGRADE	UPGRADE TO 8 PT SEQUENCER - RT/GC	\$ 3,762.00
ZS07 RT CAL CONV	RT CONVERSION 1 GAS TO ANOTHER	\$ 2,486.00
ZS07 RT CAL CONV+1	RT CONVERSION TO ADD 1 GAS	\$ 2,876.00
ZS07 EXPEDITE	PREMIUM EXPEDITE FEE	\$ 920.00
ZS07CG5K4-16UPG	UPGRADE 4 PT TO 16 PT SEQUENCER - CG5000	\$ 6,713.00
ZS07CG5K4-16UPGNH3	SPGRADE 4PTTO16PT SEQUENCERAMMONIACG5000	\$ 6,568.00
ZS07CG5K4-8UPG	UPGRADE 4 PT TO 8 PT SEQUENCER - CG5000	\$ 3,197.00
ZS07CG5K4-8UPGNH3	UPGRADE 4PTTO 8PT SEQUENCERAMMONIACG5000	\$ 3,131.00
ZS07CG5K8-16UPG	UPGRADE 8 PT TO 16 PT SEQUENCER - CG5000	\$ 3,813.00
ZS07CG5K8-16UPGNH3	UPGRADE 8PTTO16PT SEQUENCERAMMONIACG5000	\$ 3,736.00
ZS07CG5KFIRMWAREUPG	FACTORY FIRMWARE UPGRADE WITH SD CARD	\$ 297.00
ZS07INSP	Perm Instrument Insp fee	\$ 225.00
ZS07INSPCHMCHL	Chemgard / Chillgard Insp fee	\$ 505.00
ZSULTREP1	ULT X SENSOR REPAIR BASED ON GAS CODE	\$ 582.00
ZSULTREP2	ULT X SENSOR REPAIR BASED ON GAS CODE	\$ 643.00
ZSULTREP3	ULT X SENSOR REPAIR BASED ON GAS CODE	\$ 990.00

NOTE: MSA DOES NOT SERVICE CHILLGARD MONITORS MADE PRIOR TO NOVEMBER 1998

*All other repairs to Permanent instrument products not covered by a flat rate fee above will be subject to time and material billing for which MSA Service will supply an estimate / quote. If warranty conditions do not apply or if you choose not to proceed with repairs upon receiving the estimate / quote, then a minimum service / inspection fee of \$225.00 dollars or \$505.00 dollars for Chemgard / Chillgard products will apply.