




3MTM AttestTM Vaporized Hydrogen Peroxide Tri-Metric Chemical Indicator, Type 4


Unprocessed



Processed




ACCEPT



ACCEPT



ACCEPT



ACCEPT

3MTM AttestTM Vaporized Hydrogen Peroxide Tri-Metric Chemical Indicators, Type 4 comply with ISO 11140-1:2014.

If a color change to pink has entered the ACCEPT zone it is considered a pass.

Processed



REJECT



REJECT



REJECT

If a color change to pink has not entered the ACCEPT zone, it is considered a fail.

Please reference the instructions for use for additional information.