

Declaration of Conformity

We, at General Monitors Inc, hereby declare that the equipment described below, both in its basic design and construction, and in the version or versions marketed by us, conforms to the relevant safety and health related requirements of the appropriate EU Directives, only as follows:

Models: FL3100H & FL3101H Flame Detectors

a) Conform to the protection requirements of EMC Directive 2014/30/EU.
Report Number D90212Q1 (Dated 2/09) by Compatible Electronics, 19131 El Toro Rd, Lake Forest, CA 92676.

Relevant Standards: EN 50130-4 EN 61000-6-4

b) Sira Certification Service, Unit 6 Hawarden Industrial Park, Hawarden, CH5 3US, United Kingdom, notified body number 0518 in accordance with Directive 2014/34/EU, certifies that this equipment has been found to comply with the Essential Health and Safety Requirements relating to the design and construction of equipment intended for use in potentially explosive atmospheres given in Annex II to the Directive. Certificate No. SIRA 09ATEX1198X.

Relevant Standards:

EN 60079-0: 2012/A11:2013

EN 60079-1: 2014 EN 60079-31: 2014



II 2 G D Ex db IIB+H₂ T5 Gb Ex tb IIIC T100°C Db

ate: Sep. 06

It is ensured through internal measures, our ISO 9001:2008 and PQAN certifications as issued by Sira Certification, Notified Body 0518 for General Monitors Ireland and UL Demko, Notified Body 0539 for General Monitors Lake Forest that series production units conform at all times to the requirements of these current EU Directives and relevant standards.

The CE marking on the products and/or/their/packaging signifies that General Monitors holds the reference technical file available to the European Union authorities.

Responsible Person:

Cecil Lenihan

Business Leader Galway, Ireland

The signatory acts on behalf of company management, and with full power of attorney.



General Monitors Inc. 26776 Simpatica Circle Lake Forest, CA 92630 United States

Phone: +1.949.581.4464

General Monitors Ireland Ballybrit Business Park Galway, Ireland Phone: +353-91-751175

www.MSAsafety com/detection

